



Technical Bulletin

TB 0206 - Inaccessible customer points of attachments

Purpose

The purpose of this technical bulletin is to inform Endeavour Energy employees and contractors of the procedure for rectifying defects on a Point of Attachment (POA) that is inaccessible.

Background

On customers' premises, additions and changes to structures and external fittings can disrupt access to the customer's POA. This is a hazard when there is a defect on the POA, as it cannot be accessed for maintenance or defect rectification. Under no circumstances should Endeavour Energy employee's or contractors compromise their safety by climbing onto a structure that is not designed for that purpose.

Actions

When a POA is identified as inaccessible, a defect shall be raised against the customer to be rectified within one month to either:

- a) Remove the offending structure permanently OR
- b) Relocate the POA to an easily accessible location. This option must be carried out by an Accredited Service Provider.

Impacted Standards

The contents of this technical bulletin will be included in the next update of the following standard(s):

- MMI 0001 – Pole and line inspection and treatment procedures