




TRANSFORMER CONDUITS - FOUR CABLES PER PHASE
CONDUITS:-12x150NB & 1x100 NB. FOR EARTHING.



TRANSFORMER CONDUITS - THREE CABLES PER PHASE
CONDUITS:- 9x150NB & 1x100 NB. FOR EARTHING.



TRANSFORMER CONDUITS - TWO CABLES PER PHASE
CONDUITS:- 6x150NB & 1x100 NB. FOR EARTHING.



TRANSFORMER CONDUITS - ONE CABLE PER PHASE
CONDUITS:- 3x150NB & 1x100 NB. FOR EARTHING.

ABBREVIATIONS:
EE - ENDEAVOR ENERGY
WT - WARNING TAPE
NB - NOMINAL BORE
OD - OUTSIDE DIAMETER
HD - HEAVY DUTY
HV - HIGH VOLTAGE
LV - LOW VOLTAGE